Summary Water Bodies Assessment and Recommendation Report Approved by the Arlington Conservation Commission on December 17, 2015

The Arlington Conservation Commission has carried out an initial assessment of fourteen water bodies in the Town of Arlington, which include five lakes and ponds and nine streams. A majority of these are negatively impacted by polluted runoff and stormwater discharges due to the highly urban nature of Arlington and surrounding towns. Most of these water bodies also have excessive aquatic invasive plants that degrade water quality, impede recreational use, and degrade aesthetics. In determining which waterbodies could benefit from management measures using Town funding, we have taken a triage-based approach:

- Water bodies that are in generally good shape that do not need much help, or whose issues are being addressed by other agencies or funding sources, e.g., Upper & Lower Mystic Lakes and Upper Mystic River
- 2. Water bodies with some issues that could benefit from directed intervention, e.g. Spy Pond, Arlington Reservoir, Hills Pond, Reeds Brook
- 3. Water bodies that are in poor shape with many issues that would need major efforts and thus funding to improve, e.g. Mill Brook, Alewife Brook.

Based on our analysis we have identified the following five priority locations for attention in the coming year:

- Arlington Reservoir Town-owned water body in Arlington and Lexington with aquatic
 invasive water chestnuts that form dense, impenetrable mats at the water's surface, which impair
 public use and water quality. Recommend continuation of current management practices to
 mechanically remove water chestnuts. In the future, when the water chestnuts' seed bank is
 depleted, the harvesting could be taken on by volunteers.
- **Hills Pond** Small pond in a very heavily used park with water quality and invasive plant problems. Recommend review and modification of current management practices for greater use of non-chemical treatment (e.g., aeration) for invasive plant control.
- Mill Brook The very poor water quality (EPA/MyWRA 2014 rating of D-) is primarily due to storm water runoff; however, the brook and its adjacent shore provide valuable wildlife habitat and opportunities for nature views. Some areas are attractive natural areas and efforts should be made to enhance public access. A possible effort might be invasive plant control along the banks and adjacent areas. In addition, the Working Group recommends that the Town DPW prioritize pretreatment stormwater improvements in the drainage area of Mill Brook to improve the water quality, since this is the most highly impacted Water Body in Arlington.
- Reeds Brook Retention Ponds at McClennen Park These are small constructed ponds that
 have major value for storm control and provide wildlife habitat. Recommend professional
 analysis of current conditions and management practices to improve the wildlife nesting habitat.
 Analysis recommendations may include additional native vegetation, reduction of mowed grass
 areas, and restriction of off-leash dog activities. Also an operation and management plan should
 be created for this area.

• **Spy Pond** – Heavily used by public for recreation with invasive plant problems in and around the pond that impair use; also erosion along portions of the shoreline. Recommend assessment, design review and implementation of shoreline erosion control, updating or creating the operation and management plan, and continuation of aquatic invasive plant management practices.

The Water Bodies Working Group has generated an assessment table of all Water Bodies evaluated in support of this report (attached). We recommend that other locations that have not been identified above as a priority for Town Water Bodies funding for FY16 should continue to be monitored, and recommendations for actions and funding should be reviewed on an annual basis.

Respectfully Submitted by:

Water Bodies Working Group of the Arlington Conservation Commission:

David White Susan Chapnick Chuck Tirone

17 December 2015